


Publication T1-725, Rev. A Dated: June 29, 2001

## **ILLUSTRATED PARTS BREAKDOWN**





From Tech Development Inc 6800 Poe Ave. •Dayton OH 45414

Tel: (937) 898-9600 •Fax: (937) 898-8431 Website: tdiairstarters.com

FROM TECH DEVELOPMENT INC.

## TOP ASSEMBLY PART NUMBERS COVERED IN THIS PUBLICATION

PART NUMBER	IN PORT	OUT PORT	O-RINGS	OVERHAUL KIT
RLVA-25683-001-1	1 ¼″	1 1⁄4″	Buna-N	2-26119-001
RLVA-25683-001-2	1 ¼″	1 1⁄4″	Viton	2-26119-002
RLVA-25683-001-1-01	1 1⁄2″	1 1⁄2″	Buna-N	2-26119-001
RLVA-25683-001-2-01	1 1⁄2″	1 1⁄2″	Viton	2-26119-002

KEY NO.	DESCRIPTION	PART NUMBER	
1	Housing, Relay Valve (1 ¼″ NPT)	2-25764	
1	Housing, Relay Valve (1 ½″ NPT)	2-25764-001	
2	O-Ring, Buna - N	9-90001-221	
2	O-Ring, Viton	9-90002-221	
3	O-Ring, Buna - N	9-90031-324	
3	O-Ring, Viton	9-90030-324	
4	Piston	2-25694	
5	Dampener, Shock	2-25107	
6	Cap, O-Ring	2-25106	
7	Spring, Compression	9-90435	
8	O-Ring, Buna - N	9-90001-218	
8	O-Ring, Viton	9-90002-218	
9	End Cap	2-25693	
10	O-Ring, Buna - N	9-90001-035	
10	O-Ring, Viton	9-90002-035	
11	Ring, Retaining	9-92001-016	

## **TDI** *TURBOVALVE***<sup>TM</sup>** FROM TECH DEVELOPMENT INC.

